

POWERMADD[®] Loop Blackout

Installation Instructions for Part No. 15894 thru 15898

HARDWARE INLCUDED:

<u>Qty</u>	<u>Description</u>
------------	--------------------

1	Loop Blackout
5	Cable Ties

STEP 1: Pick which ski you want the Loop Blackout installed and insert in into the loop.

STEP 2: Insert a cable tie through each of the holes in the Blackout, then tighten each cable tie around the loop.

STEP 3: Trim the excess off of each cable tie.

LIMITED WARRANTY

POWERMADD warrants this product to be free from defects in material and workmanship under use for the purpose it was intended. **POWERMADD** shall not be liable for damage or injury caused by defective materials or workmanship.

POWERMADD may elect to repair or replace this product, but is the sole judge of any defects in their product. This warranty does not cover any labor costs to remove or reinstall this product and is effect for one year from the original purchase date.

POWERMADD[®]

1-800-435-6881

www.powermadd.com

WEB-INS-5 REV A